

## **SAND HILL LAKES MITIGATION BANK**

Oblique Aerials – 30 October 2007



Cypress swamp and littoral zones at Dry Pond.



Looking northeast across Boggy Branch; note removal of pine plantation from center polygon; Chain Lake Rd. to right.





Looking north; Cat Pond foreground; Deep Edge Pond middle ground; note oak reduction areas.



Looking west; Cat Pond; note two erosion stabilization sites and oak reduction areas.





Looking southeast; Cat Pond middle left (sand pine plantation middle right is off property).



Looking northeast; Warmouth Pond foreground; Black Pond middle left; Dry Pond upper left; Dykes Mill Pond upper right.





Looking northeast across Dykes Mill Pond; note pine plantation removal upper right.



Looking northeast across Dykes Mill Pond and pine plantation removal areas.





Looking northwest; Dykes Mill foreground; Black Pond upper left; Dry Pond upper right.



Looking northeast; note oak reduction and pine plantation removal; Joiner Lake (offsite) in middle ground.





Looking north-northwest; Dykes Mill Pond on left; Garrett Pond (dry) center right; Dry Pond in background.



Looking southwest; Dykes Mill Pond upper right; Deep Edge Pond upper left; note pine removal and oak reduction.





Looking southwest; Dykes Mill Pond in top of image.



Looking southwest across Garrett Pond (foreground) and Dykes Mill Pond (background).





Looking south; Garrett Pond lower right; Dykes Mill Pond middle right.



Looking south; Dry Pond upper right; note extensive brush reduction (Gyro-track) areas and wildfire damage.





Looking south; note wildfire damage and extensive brush reduction (Gyro-track) areas.



Looking south across Dry Pond; note brush reduction (Gyro-track) area in foreground.





Looking southeast; Green Ponds lower left; Dry Pond upper right.



Looking northeast across Green Ponds.





Looking east across Green Ponds; note extensive brush reduction (Gyro-track) area in middle ground.



Looking northeast across Green Ponds.





Looking northeast across Green Ponds.



Looking north across brush reduction (Gyro-track) area.





Looking northeast across extensive brush reduction (Gyro-track) area, with wildfire damage to left.



Looking north across extensive brush reduction (Gyro-track) areas; Garrett Pond lower right; cypress swamp on left.





Looking northwest across Garrett Pond; extensive brush reduction (Gyro-track) in middle ground.



Looking north; Dykes Mill Pond to left; Garrett Pond center; Joiner Lake upper right.





Looking northeast toward Joiner Lake.



Looking north toward Joiner Lake; Garrett Pond (dry; white sand) middle/upper left.





Looking west across FWCC check station; southern boundary (Chain Lake Rd.) of SHLMB to left.



Looking southwest; note extensive pine and oak removal (pine stands in upper portion of image removed 11/07).





Looking south-southwest across Little Deep Edge Pond.



Looking southwest across Power Line Pond; note new bridge in middle right.





Looking southwest across Warmouth Pond; note Pine Log Swamp in upper left.



Looking east; Black Pond to right and Dry Pond to left; note brush reduction (Gyro-track) in middle ground.





Looking east; Black Pond to right and Dry Pond to left; note brush reduction (Gyro-track) between ponds.



Looking north across Point Point No. 7; Black Pond to right.





Looking north across Black Pond (foreground) and Dry Pond (background).



Looking northeast across oak reduction area and Dykes Mill Pond.





Looking northeast; Little Deep Edge Pond foreground; Dykes Mill Pond middle to background.



Looking north; Little Deep Edge Pond (separated into three pools).





Looking northwest; Greenhead Branch and unnamed tributary on right flowing to Dykes Mill Pond.



Looking northwest; Greenhead Branch flowing from right to left across image.





Looking northwest; pine in foreground removed 11/07; Deep Edge and Little Deep Edge ponds upper left.



Looking northwest; Deep Edge and Little Deep Edge ponds in upper middle ground.





Looking southwest over pine plantation removal operations; Chain Lake Rd. upper left.



Looking west; Deep Edge Pond upper right; Little Deep Edge Pond far right.





Looking west across Little Deep Edge Pond; note road removal in foreground.



Looking west across Little Deep Edge Pond; note cloud reflection in Deep Edge Pond at top of image.





Looking west across arm of Dykes Mill Pond; note wet meadow properties.



Looking west across arm of Dykes Mill Pond; Pine Log Swamp in background.





Looking southwest across Dykes Mill Pond; Black Pond to upper right.



Looking west across Black Pond.





Looking south across cypress swamp and Dry Pond; Black Pond in background; wildfire damage apparent in lower left.